

Sanitary Repairs Buildings J & K *Project Photos*

January 3, 2003



One of the project tunnel entries.



Exposed piping and bracing under building.



Existing pipe and tunnel entry, Hydro-excavated and shored.



New piping and braces installed after tunneling.



New piping and bracing, installed after tunneling by Bravo crew.



New piping installed after hydro-excavating next to building footer.

Sanitary Repairs
Buildings J & K
Project Photos

January 3, 2003



Project scope was to replace all plumbing under occupied building. Bravo Environmental performed all excavations and shoring around and under building, including safety plan, daily safety meetings for all work crews.