

Your company - 35849 Reston Rd S - Shelton - WA 800.123.4567

Smoke Test - City of Westberg

City of Westberg

Westberg, OR

12/21/2001



Category: Cleanout

Image : 225 E 10th St

Video Ref: 01600 **Severity:** 2

Location: 225 E 10th St

Description: There is broken cleanout cap on the side of the house. Two vents on the back of the house could be extended above the roof line.



Category: No venting

Image : 248 E 10th St

Video Ref: 01602 **Severity:** 2

Location: 248 E 10th St

Description: This house has no apparent external sanitary venting. Smoke is coming from a pipe at the base of the foundation on the side of the house. The house is vacant, it filled with smoke, indicating open vents or P-traps.



Category: Not on system

Image : 1115 Aspen Ave

Video Ref: 01602 **Severity:** 3

Location: 1115 Aspen Ave